

Inspection Photos
Location Name: Parker #2
Location ID: 333125



Photo 1 WH



Photo 2 Stained soil WH

Inspection Photos
Location Name: Parker #2
Location ID: 333125



Photo 3 Stained soil PU motor



Photo 4 Stained soil PU exhaust

Inspection Photos
Location Name: Parker #2
Location ID: 333125



Colorado Oil and Gas Conservation Commission
40.11865, -104.81771, 1468.6m
Dec 26, 2018 08:58:14

Photo 5 Propane tank Unused equipment