

**Inspection Photos**  
**Location Name: Parker #1**  
**Location ID: 336465**



**Photo 1 PU**



**Photo 2 Unused equipment**

**Inspection Photos**  
**Location Name: Parker #1**  
**Location ID: 336465**



**Photo 3 Stained soil PU motor**



**Photo 4 Unused equipment (Fence)**



**Inspection Photos**  
**Location Name: Parker #1**  
**Location ID: 336465**




**Photo 5 fuel gas leak on VLV**



**Photo 6 Unused equipment Propane tank**

**Inspection Photos**  
**Location Name: Parker #1**  
**Location ID: 336465**



**Photo 7 Pull plug does not have plug**



**Photo 8 Leaking fuel gas line to ECD**



Inspection Photos  
Location Name: Parker #1  
Location ID: 336465



Photo 9 TNK BTRY



Photo 10 Stained soil crude oil tank