

Inspection Photos
Location Name: Millard #43-30
Location ID: 333199



Photo 1 WH

Photo 2 TNK BTRY

Inspection Photos
Location Name: Millard #43-30
Location ID: 333199



Photo 3 Stained soil outside SEP



Photo 4 Stained soil inside SEP

Inspection Photos
Location Name: Millard #43-30
Location ID: 333199



Photo 5 Stained soil at WH