

Inspected Facilities			
Facility ID: <u>422731</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u> Insp. Status: <u>AO</u>
Producing Well			
Comment: <u>PR</u>			
Corrective Action:		Date:	
Complaint			
Comment: <u>Inspection in response to complaint. Form 18- #200446804</u> <u>Field Inspector Assigned: Tom Peterson</u> <u>Complaint Received:</u> <u>Date: 12/13/2018</u> <u>Complaint Contacted: Anonymous</u> <u>Date:</u> <u>Location #: 422731</u> <u>Inspection Document #: 674301356</u> <u>Nature of complaint: Noise</u> <u>Field Inspector Actions:</u> <u>On 12/19/2018; I received a complaint in regard to noise on the Fredriksen 1B 28H H368 location, owned and operated by Crestone Peak Resources.</u> <u>On 12/20/2018, I performed a site inspection, I found a recently installed hydraulic pumping unit powered by a natural gas engine.</u> <u>A sound study was conducted in accordance with Rule 802c.</u> <u>Results show average DB @ 52.9. COGCC noise survey results indicate noise levels exceed limits in Rule 802.</u> <u>See inspection document for corrective action detail.</u> <u>All information reviewed and site inspection information were submitted to the complaint specialist for further review.</u>			
Corrective Action: <u>Comply with Rule 802. Identify and install control measures.</u>			Date: <u>12/21/2018</u>

Attached Documents

You can go to COGCC Images (<https://ogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401882135	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4683875
674301257	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4683873
674301258	Sound survey	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4683874