

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/17/2018

Submitted Date:

12/20/2018

Document Number:

682600588**FIELD INSPECTION FORM**Loc ID 322274 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 17210Name of Operator: CINNAMON CREEK OIL & GAS INCAddress: P O BOX 544City: WALSH State: CO Zip: 81090**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_COGCCengineering@state.co.us	COGCC Engineering
Mills, Rick	719-324-5630/719-353-2523	rickmills000@gmail.com	All Inspections
Axelson, John		john.axelson@state.co.us	COGCC East Environmental Supervisor
Hasty, Tim	(719) 429-3529/ (719) 340-0329	thhasty@gmail.com	All Inspections
,		dnr_cogccenforcement@state.co.us	COGCC Enforcement
Mills, Helen		heleningle1221@yahoo.com	All Inspections
Sutphin, Dirk		dirk.sutphin@state.co.us	COGCC Area Engineer
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210097	WELL	PR	05/23/2011	OW	043-40034	LOBACH 1	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Inspection found 1 inch ball valve venting gas at the time of inspection without prior approval from the COGCC as required per Rule 912.b

Operator contacted via phone to cease venting.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Truck Loadout	<= 1 bbl		
Comment: Stained soil inside containment at truck loadout.				
Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.			Date:	01/21/2019

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	YES		
Comment:	Gas being vented or flared during non-upset condition without prior approval from COGCC. Gas is venting from 1" line north of wellhead. COGCC Inspection 687900019 on 5/24/2017 required operator to file Form 4 about venting to the area engineer. At the time of this inspection no Form 4 has been filed with the COGCC. Corrective Action date is from previous inspection 687900019.		
Corrective Action:	Since the flaring or venting occurred after flowback without approval, contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details.		Date: 06/24/2017

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 210097 Type: WELL API Number: 043-40034 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401882014	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4683772
682600589	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4683770