

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2018

Submitted Date:

12/21/2018

Document Number:

688800399**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Hughes, Jim 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Baca, Matthew		matthew.baca@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459307	SPILL OR RELEASE	AC	12/10/2018		-	Richardson G 2	EI

General Comment:

On December 14, 2018 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the BP Richardson G #2 Spill/Release Point ID #459307. For the most recent field inspection report of this facility, please refer to document #688800397. A construction crew was excavating the pipeline in preparation of replacing the damaged section during this inspection.

Location

Lease Road:			
Type	Access		
comment:	Dirt and gravel access road. Release occurred near pipeline road crossing.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Carsonite pipeline markers indicate pipelines cross access road near release point.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Safety fencing present around excavation on east side of access road at the time of this inspection. Jersey barriers along both sides of access road.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 60

Comment: Please refer to Initial Spill/Release Report Document #401866521 for more information regarding this release.

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. The operator shall submit a Form 27 Site Investigation and Remediation Workplan by the corrective action date. Contact COGCC EPS staff regarding Rule 906.c.

Date: 01/11/2019

Reportable: YES

GPS: Lat 37.238919

Long -107.697998

Proximity to Surface Water: 500

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location: Comment:

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
	Piles	Inadequate	37.238919	-107.697998
Comment	Impacted material has been excavated to expose pipeline through work area. Install storm water BMPs to prevent migration of impacted soil, or contaminants from the work site.			
Corrective Action	E&P waste not properly stored, handled, transported, treated, recycled, or disposed of per Rule 907. Contact COGCC EPS staff.			Date: 12/24/2018

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	Prevent contaminant migration.

Comment: [Install BMPs to prevent migration of impacted soil, or remove from site.](#)

Corrective Action:

Date: 12/24/2018

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On December 14, 2018 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the BP Richardson G #2 Spill/Release Point ID #459307. For the most recent field inspection report of this facility, please refer to document #688800397. A construction crew was excavating the pipeline in preparation of replacing the damaged section during this inspection.</p> <p>The release point had reportedly not been discovered at the time of this inspection. The 3" fiberglass pipelines were observed to be drooping as they came out of the 12" casing sleeve and between the sandbag supports.</p> <p>Impacted material was being stockpiled alongside the excavations. The operator shall ensure that the excavated material and contaminants do not migrate.</p>	hughesjo	12/21/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401885088	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4686254
688800400	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4686253