

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2018

Submitted Date:

12/21/2018

Document Number:

689302725**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 322325      Holtz, Darin      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10550Name of Operator: MUSTANG RESOURCES LLCAddress: 1660 LINCOLN STREET SUITE 1450City: DENVER      State: CO      Zip: 80264**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Coutts, Brandon		bcoutts@mustangresourcesllc.com	
Murray, Richard		g.richard.murray@state.co.us	Pipeline group
Lemon, Deb		dlemon@mustangresourcesllc.com	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210278	WELL	PR	12/01/2016	GW	045-06034	JUHAN RULISON UNIT 34-94-6S-94W	PR

**General Comment:**

Routine Field Inspection.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: 1-888-291-8588

Corrective Action:

Date:

**Good Housekeeping:**

Type UNUSED EQUIPMENT

Comment: Unmarked flow line, see photo

Corrective Action: Comply with rule 603.f.  
For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser, mark as required.

Date: 01/21/2019

Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	210278	Type:	WELL	API Number:	045-06034	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401884824	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4686053">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4686053</a>
689302726	Inspection photo 689302726	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4686043">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4686043</a>