

Inspection Photos

Location Name: Homer Deep Unit 7-23

Location ID: #436835 Spill/Release ID: #460341

Inspection Date: December 27, 2018



Photo #1 – Sign located at tank battery.



Photo #2 – View of tank battery/spill location from southwest.

Inspection Photos

Location Name: Homer Deep Unit 7-23

Location ID: #436835 Spill/Release ID: #460341

Inspection Date: December 27, 2018



Photo #3 – View of tank heater, surface flowline, and ditch east of tank battery.



Photo #4 – 1" flowline riser protruding through liner at south end of tank battery.

Inspection Photos

Location Name: Homer Deep Unit 7-23

Location ID: #436835 Spill/Release ID: #460341

Inspection Date: December 27, 2018



Photo #5 – Additional 1" flowline risers protruding through liner along east side of tank battery.



Photo #6 – Flowline riser and electrical conduit protruding through liner north of produced water AST. Note: other ASTs in tank battery had the same flowline configuration.

Inspection Photos

Location Name: Homer Deep Unit 7-23

Location ID: #436835 Spill/Release ID: #460341

Inspection Date: December 27, 2018



Photo #7 – 2" Flowline risers protruding through liner on west side of tank battery.



Photo #8 – Chemical storage tanks with secondary containment devices located south of tank battery.

Inspection Photos

Location Name: Homer Deep Unit 7-23

Location ID: #436835 Spill/Release ID: #460341

Inspection Date: December 27, 2018



Photo #9 – Shed located south of tank battery.



Photo #10 – Oil-stained gravel on southeast side of shed.

Inspection Photos

Location Name: Homer Deep Unit 7-23

Location ID: #436835 Spill/Release ID: #460341

Inspection Date: December 27, 2018



Photo #11 – 300 bbl sand tank inside of metal SPCC, located west of wellheads.



Photo #12 – Metal rod stored inside of east side of sand tank SPCC.

Inspection Photos

Location Name: Homer Deep Unit 7-23

Location ID: #436835 Spill/Release ID: #460341

Inspection Date: December 27, 2018



Photo #13 – Gap observed between liner panels inside southeast corner of sand tank SPCC.



Photo #14 – Unused flowline risers observed west of separators.

See R. Murray's 12/27/2018 Integrity Inspection for corrective actions related to flowlines and flowline risers.

Inspection Photos

Location Name: Homer Deep Unit 7-23

Location ID: #436835 Spill/Release ID: #460341

Inspection Date: December 27, 2018



Photo #15 – Pig station and surface flowlines located north of crude oil/produced water tank battery.

See R. Murray's 12/27/2018 Integrity Inspection for corrective actions related to flowlines and flowline risers.



Photo #16 – ECD and surface flowlines located along north side of well pad.

See R. Murray's 12/27/2018 Integrity Inspection for corrective actions related to flowlines and flowline risers.