

**Inspection Photos**  
**Location Name: JW POWEL #23-35**  
**Location ID: 459837**



**PHOTO 1: DRILLING RIG**



**PHOTO 2: RIG SIGN**

**Inspection Photos**  
**Location Name: JW POWEL #23-35**  
**Location ID: 459837**



**PHOTO 2: ROW PRIOR TO CONSTRUCTION**



**PHOTO 3: LOCATION PRIOR TO CONSTRUCTION**



**Inspection Photos**  
**Location Name: JW POWEL #23-35**  
**Location ID: 459837**



**PHOTO 5: NO BERMS ON LOWER SIDE OF LOCATION**



**PHOTO 6: NO BERMS ON LOWER SIDE OF LOCATION**

**Inspection Photos**  
**Location Name: JW POWEL #23-35**  
**Location ID: 459837**



**PHOTO 7: DITCH FOR STORM WATER DRAINAGE OF UP HILL SIDE  
OF LOCATION DOES NOT RUN CONTINUOUS ACROSS LOCATION**