

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers No volume sign on tank		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	02/26/2019

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil inside sep house and around PU		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	12/26/2018

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Inadequate fencing or Fencing in disrepair		
Corrective Action:	Location is within a designated setback location, install fencing per Rule 604.c.(2)M.	Date:	01/16/2019
Type	SEPARATOR		
Comment:	Inadequate fencing or Fencing in disrepair		
Corrective Action:	Location is within a designated setback location, install fencing per Rule 604.c.(2)M.	Date:	01/16/2019
Type	WELLHEAD		
Comment:	Steel pipe		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
--------------------	-----	--	-----------------

Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas powered motor		
Corrective Action:			Date:
Type: Gas Meter Run	# 0		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.107492,-104.815562
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tank. No volume sign on tank			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 246797 Type: WELL API Number: 123-14594 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
This is a follow up inspection per Doc#691401580. All corrective actions have not been addressed at time of inspection.	silverr	12/26/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401886267	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4687221
688400953	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4687218