

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/31/2018

Submitted Date:

01/02/2019

Document Number:

693200208**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection
436835 _____ Murray, Richard _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Bankert, Wayne	(970) 683-5419	cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437387	WELL	PR	07/22/2017	OG	045-22423	Homer Deep Unit 7-23AH	EG
440891	WELL	WO	04/03/2015	LO	045-22809	Homer Deep Unit 7-23DH	EG
440892	WELL	PR	07/01/2017	GW	045-22810	Homer Deep Unit 7-23BH	EG
440893	WELL	WO	04/02/2015	LO	045-22811	Homer Deep Unit 7-23CH	EG
442672	WELL	AL	05/09/2018	LO	045-22892	Homer Deep Unit 7-23EH	EG

General Comment:

[Joint inspection with Steven Arauza and Richard Murray](#)

[Engineering Integrity Inspection performed on Decenber 27, 2018 . In response to initial form 19 spill report Doc #401885635](#)

[Photo's uploaded can be accessed via link\(s\) at the end of report.](#)

[Cause of release appears to be failure of the tank due to corrosion but this is still under investigation,](#)

[: Email information outlined below to COGCC Inspector, Establish root cause of the failure and discuss measures that will be taken to prevent reoccurrence](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	10" poly lines around location and steel flowlines		
Corrective Action:	Comply with Rule 603.f. 90 days for unused equipment when machinery is required to remove the equipment	Date:	04/02/2019
Type	UNUSED EQUIPMENT		
Comment:	6 risers at separators, 2 risers on north side of location, 4 risers at wellhead, See photos		
Corrective Action:	Comply with Rule 603.f . For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.	Date:	02/01/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>437387</u>	Type: <u>WELL</u>	API Number: <u>045-22423</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>440891</u>	Type: <u>WELL</u>	API Number: <u>045-22809</u>	Status: <u>WO</u>	Insp. Status: <u>EG</u>
Facility ID: <u>440892</u>	Type: <u>WELL</u>	API Number: <u>045-22810</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>440893</u>	Type: <u>WELL</u>	API Number: <u>045-22811</u>	Status: <u>WO</u>	Insp. Status: <u>EG</u>
Facility ID: <u>442672</u>	Type: <u>WELL</u>	API Number: <u>045-22892</u>	Status: <u>AL</u>	Insp. Status: <u>EG</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200209	Homer Deep	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4691740