

Inspection Photos

Operator: Hilcorp Energy

API: 05-067-09461

Date: 12/19/2018



Photo 1. View of the southern project area from the southwestern corner facing eastward.



Photo 2. View the eastern project area from the southwestern corner facing center.



Photo 3. View of jointed goatgrass (*Acroptilon repens*) within the northwestern project area. Also present within the northeastern project area.



Photo 4. View of kochia debris within the western project area. Debris needs to be removed and properly disposed of.



Photo 5. View of unmarked anchor at the northern entrance to the project area.