

# Inspection Photos


1/03/2019

Operator: MURFIN DRILLING COMPANY INC -  
61650

Location ID: 387013

Inspection Doc. Number: 682504357  
Lincoln County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the northwest end of the location, facing southwest. Photo 1-3 provide and overview of the location. Photo shows location remains predominantly bare and exposed soil; location does not meet reclamation requirements.






**Photo 2:** Photo taken from the northwest end of the location, facing south. Photo 1-3 provide an overview of the location. Photo shows location remains predominantly bare and exposed soil; location does not meet reclamation requirements.





**Photo 3:** Photo taken from the northwest end of the location, facing east. Photo 1-3 provide an overview of the location. Photo shows location remains predominantly bare and exposed soil; location does not meet reclamation requirements.





**Photo 4:** Photo taken from the north end of the location, facing southwest. Photo shows location remains predominantly bare and exposed soil; location does not meet reclamation requirements.





**Photo 5:** Photo taken from the southwest end of the location, facing east. Photo shows location remains predominantly bare and exposed soil; location does not meet reclamation requirements.





**Photo 6:** Photo taken from the southwest end of the location, facing southwest. Photo shows stormwater runoff from location causing erosion degradation.





**Photo 7:** Photo taken from location. Photo shows location remains predominantly bare and exposed soil.





**Photo 8:** Photo taken from the adjacent reference area. Photo shows reference vegetation. Vegetation observed includes Blue grama, Buffalo grass, Wester wheat, Purple threeawn, sand dropseed, etc...