

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/08/2019

Submitted Date:

01/08/2019

Document Number:

691401811**FIELD INSPECTION FORM**
 Loc ID 413766 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|--------------|----------------------|---------------------------------|
| ROYBAL, JAMES | 719-845-4323 | james.roybal@pxd.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 411856 | WELL | PR | 09/16/2011 | GW | 071-09766 | Pointer 43-25 | PR |
| 426786 | PIT | AC | 12/08/2011 | | - | POINTER 43-25 | AC |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | LOCATION | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|-------------|
| Emergency Contact Number: | |
| Comment: | |
| Corrective Action: | Date: _____ |

| | | |
|---------------------------|---|------------------|
| Good Housekeeping: | | |
| Type | OTHER | |
| Comment: | STAINED SOIL BENEATH DRIVEHEAD HYRAULIC CONNECTIONS. SEE LOC PICS | |
| Corrective Action: | Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. | Date: 02/08/2019 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | |
|--------------------|-----|-------|
| Fencing/: | | |
| Type | PIT | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | |
|--------------------|----|-------|
| Venting: | | |
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | |
|--------------------|--|-------|
| Flaring: | | |
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|------------------------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 411856 | Type: | WELL | API Number: | 071-09766 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | PR | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| BradenHead | | | | | | | | | |
| Comment: | | NOT PLUMBED TO SURFACE | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 426786 | Type: | PIT | API Number: | - | Status: | AC | Insp. Status: | AC |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: YESPit ID: 426786Lat: 37.229480Long: -104.832000Reference Point: SE

Other: _____

Length: 40Width: 20**Lining:**Liner Type: OtherLiner Condition: InadequateComment: No liner or liner not maintained LINER HAS HOLE AND TEARS SEE ATTACHED PHOTOS

Corrective Action

Lack of pit liner or pit liner compromised (Rule 904). REMOVE OR REPLACE LINERDate: 03/08/2019**Fencing:**Fencing Type: LivestockFencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: YESOil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

| Permit: | Facility ID | Permit Num | Expiration Date |
|---------|-------------|------------|-----------------|
| | 426786 | 2221467 | |

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| <u>Followup inspection to inspection doc 682600515. Corrective actions appear to have been completed.</u> | beardslt | 01/08/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 691401812 | LOC PICS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4698054 |