

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2019

Submitted Date:

01/09/2019

Document Number:

679300076

FIELD INSPECTION FORM

Loc ID 326882 Inspector Name: Graber, Candice (Nikki) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10311
Name of Operator: SRC ENERGY INC
Address: 1675 BROADWAY SUITE 2600
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dave Castro		dcastro@srcenergy.com	
,		cogccinspections@srcenergy.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446169	TANK BATTERY	AC	06/14/2016		-	GARCIA K 04-30D	EI
446572	SPILL OR RELEASE	CL	07/13/2016		-	Garcia 1-5	EI

General Comment:

This is an environmental inspection in response to NFA request on Remediation #9782. Any corrective actions from previous inspections that have not been addressed are still applicable.
Photos attached to document site condition at the time of inspection.

Location

Overall Good:

Emergency Contact Number:

Comment: Good

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: None observed

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 446169 Type: TANK API Number: - Status: AC Insp. Status: EI

Facility ID: 446572 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spill/Remediation:

Comment: Monitoring wells are in place and appear in good condition. SVE hoses still attached and are on the south side of location. Monitoring wells and all other remediation equipment shall be removed within 90 days of NFA.

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679300077	Site Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4698494
679300078	Site Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4698495