

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/26/2018

Submitted Date:

01/03/2019

Document Number:

682600596**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 321587 Kosola, Jason 2A Doc Num: _____

Operator Information:OGCC Operator Number: 70430Name of Operator: PINTAIL PETROLEUM LTDAddress: 225 N. MARKET #300City: WICHITA State: KS Zip: 67202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Atterbury, Mike	316-202-4956	Mike.Atterbury@darrahoil.com	All Inspections
,		pintail@pintailpetroleum.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207359	WELL	PR	03/03/1981	OW	017-06294	LOWE 4	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Above ground barrel containing crude is open to wildlife access. Netting on open tanks inadequate. Wildlife protections devices not adequate.		
Corrective Action:	Install or repair wildlife protection equipment or remove open barrel.		Date: <u>01/13/2019</u>
Type	OTHER		
Comment:	Heater treater appears to be inoperable. Vessel should be repaired or removed if not intended to be used. Vessel is open allowing wildlife access.		
Corrective Action:	Install wildlife screen per Rule 605.b.(7).		Date: <u>02/04/2019</u>

Overall Good: ☐

Spills:				
Type	Area	Volume		
Crude Oil	Tank	<= 1 bbl		
Comment:	Stained soil around tank. See attached photos.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: <u>02/04/2019</u>
Crude Oil	Pump Jack	<= 1 bbl		
Comment:	Stained soil around pump jack. See attached photos.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: <u>02/04/2019</u>

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:				corrective date
Type: Flow Line	# 4			
Comment:	Improper abandonment of flowline or crude oil transfer line (not purged, depressurized, risers cut 3' below grade, ends sealed, equipment removed) per 1105. Disconnected flowline risers not LOTO. Form 44 notice of abandonment not filed within 30 days. Local gov't designee and UNCC not contacted.			
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.			Date: <u>02/04/2019</u>

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL			STEEL AST		,	
Comment:	Tank appear to have leaked in the past or may currently have a leak. No leaking fluid was observed at the time of the inspection.					

Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	02/04/2019
--------------------	---	-------	------------

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 207359 Type: WELL API Number: 017-06294 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401892205	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4693728
682600599	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4693726