

**Inspection Photo (s)**  
**Double B ranch 18-44A**  
**API # 05-045-18782**  
**Inspection # 689302912**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo (s)**  
**Double B ranch 18-44A**  
**API # 05-045-18782**  
**Inspection # 689302912**



**Location Photo #3**



**Location Photo #4, Several unmarked flow line risers.**