

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/09/2019

Submitted Date:

01/10/2019

Document Number:

689302912

**FIELD INSPECTION FORM**

Loc ID 414152 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 18 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	Pipeline group
		COGCC.inspections@caerusoilandgas.com	all Piceance inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413361	WELL	PR	07/31/2011	GW	045-18788	Rulison Federal 20-11C (17M)	PR
413367	WELL	PR	09/23/2011	GW	045-18782	Double B Ranch 18-44A (17M)	PR
413368	WELL	PR	01/18/2012	GW	045-18781	Rulison Federal 20-11A (17M)	PR
413369	WELL	PR	08/03/2011	GW	045-18780	Rulison Federal 20-11B (17M)	PR
413372	WELL	PR	09/01/2011	GW	045-18777	Double B Ranch 18-44B (17M)	PR
413373	WELL	PR	08/29/2011	GW	045-18776	Double B Ranch 18-44C (17M)	PR
413374	WELL	PR	09/01/2011	GW	045-18775	Double B Ranch 18-44D (17M)	PR
413377	WELL	PR	07/15/2011	GW	045-18772	Rulison Federal 19-41C (17M)	PR

**General Comment:**

Routine Field Inspection.  
Location is snow covered, access is plowed open.

**ANY CORRECTIVE ACTION (S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Several unused 2" risers near separators, see photos		
Corrective Action:	Comply with rule 603.f.		Date: <u>02/09/2019</u>

Type	TRASH		
Comment:			
Corrective Action:			Date:

Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:			Date:

Type	TANK BATTERY		
Comment:	Hog panel fence.		
Corrective Action:			Date:

Type	SEPARATOR		
Comment:	Hog panel fence.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:

Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	400 BBLs	STEEL AST		,
Comment:	6 tanks in a centralized battery.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	413361	Type:	WELL	API Number:	045-18788	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	413367	Type:	WELL	API Number:	045-18782	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	413368	Type:	WELL	API Number:	045-18781	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	413369	Type:	WELL	API Number:	045-18780	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	413372	Type:	WELL	API Number:	045-18777	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	413373	Type:	WELL	API Number:	045-18776	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	413374	Type:	WELL	API Number:	045-18775	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	413377	Type:	WELL	API Number:	045-18772	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				

**Producing Well**

Comment: Well Producing on plunger lift.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302913	Inspection photo 689302913	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4699521">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4699521</a>