

Inspection Photos
Location Name: FRONT RANGE 44-10
Location ID: 308430



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: FRONT RANGE 44-10
Location ID: 308430



**PHOTO 3: STAINED SOIL UNDER DRIVEHEAD MOTOR
AROUND WELLHEAD**



**PHOTO 4: HYDRAULIC LINES ARE SATURATED INDICATING A
POSSIBLE LEAK**

Inspection Photos
Location Name: FRONT RANGE 44-10
Location ID: 308430



**PHOTO 5: APPEARS TO BE LEAKING VALVE ON SALES LINE
ATTACHED TO WELLHEAD**



PHOTO 6: LEAKING 1" VALVE ON TBG HEAD

Inspection Photos
Location Name: FRONT RANGE 44-10
Location ID: 308430



PHOTO 7: APPEARS THAT PACKING ON DRIVEHEAD IS LEAKING



PHOTO 8: TRASH INSIDE SOUND WALLS NEAR DRIVE MOTOR