

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/10/2019

Submitted Date:

01/10/2019

Document Number:

689302926

FIELD INSPECTION FORM

Loc ID 334583 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoila ndgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211181	WELL	PR	09/01/2018	GW	045-06940	PARKER RANCH 15-4	PR
274783	WELL	PR	09/01/2018	GW	045-13391	ROSE 15-4C (D15)	PR
274784	WELL	PR	08/11/2005	GW	045-13389	ROSE 15-4B (D15)	PR
274786	WELL	PR	07/24/2005	GW	045-13390	ROSE 15-5 (D15)	PR
276646	WELL	PR	08/07/2005	GW	045-10504	ROSE 16-1 (D15W)	PR
276648	WELL	PR	09/21/2010	GW	045-10505	ROSE 16-8 (D15W)	PR

General Comment:

[Routine Field Inspection.](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Emergency Contact Number:			
Comment:	1-800-791-7691		Date:
Corrective Action:			
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Flow Line riser on North end of tank battery, see photo.		
Corrective Action:	Comply with rule 603.f		Date: 02/10/2019
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Panel gates.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)	Methanol tank	
Other (Capacity)	1000 gallon	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>211181</u>	Type:	<u>WELL</u>	API Number:	<u>045-06940</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				
Facility ID:	<u>274783</u>	Type:	<u>WELL</u>	API Number:	<u>045-13391</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				
Facility ID:	<u>274784</u>	Type:	<u>WELL</u>	API Number:	<u>045-13389</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				
Facility ID:	<u>274786</u>	Type:	<u>WELL</u>	API Number:	<u>045-13390</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				
Facility ID:	<u>276646</u>	Type:	<u>WELL</u>	API Number:	<u>045-10504</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				
Facility ID:	<u>276648</u>	Type:	<u>WELL</u>	API Number:	<u>045-10505</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302927	Inspection photo 689302927	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4701189