

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2019

Submitted Date:

01/10/2019

Document Number:

688303411

FIELD INSPECTION FORM
 Loc ID 320789 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10646

Name of Operator: AXIS EXPLORATION LLC

Address: 370 17TH ST SUITE 5300

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Rickard, Jeff	720-557-08310	jrickard@extractionog.com	
Extraction	720-370-5540	COGCCInspections@extracti onog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204932	WELL	SI	01/01/2018	GW	005-07017	HSR-HILL 10-21	SI

General Comment:

Inspected FacilitiesFacility ID: 204932 Type: WELL API Number: 005-07017 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Wellhead was leaking per landowner and upon inspection it was noted as leaking through a stuffing box component. Operator brought in a temporary flare on 1/3/2019 in accordance with best management practices per COGCC Engineering to burn wellhead gas prior to working on wellhead. Pressure went from 600 psi to 10 psi during flaring per operator and flare was removed on 1/5/2019. On 1/4/2019 operator replaced stuffing box wellhead components and brought in water truck to lower well pressure to 0. On 1/7/2019 inspector rechecked the well for leaks at the wellhead and found none.

Corrective Action: _____

Date: _____

BradenHeadComment: 0 psi, Bradenhead is plumbed to surface

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688303412	Axis Exploration HSR-Hill 10-21 sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4701260
688303413	Axis Exploration HSR-Hill 10-21 temporary flare	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4701261
688303414	Axis Exploration HSR-Hill 10-21 repaired wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4701262