

## Inspection Photos

Location Name: Boies-62S98W 28SESE (#C-28P) Pad

Location ID: #335879

Inspection Date: January 11, 2019



Photo #1 – Facility sign located at access road (NE corner of pad).



Photo #2 – Well sign located north of pad.



## Inspection Photos

Location Name: Boies-62S98W 28SESE (#C-28P) Pad

Location ID: #335879

Inspection Date: January 11, 2019



**Photo #3 – Pigging station, methanol tank, and 90 bbl produced water AST located at NE corner of pad.**



**Photo #4 – Small hole in NW corner of metal SPCC liner for 90 bbl produced water AST.**



## Inspection Photos

Location Name: Boies-62S98W 28SESE (#C-28P) Pad

Location ID: #335879

Inspection Date: January 11, 2019



**Photo #5 – Methanol tank inside of secondary containment.**



**Photo #6 – Straw wattle, seen here at NE corner of pad, extends along east side of pad.**





## Inspection Photos

Location Name: Boies-62S98W 28SESE (#C-28P) Pad

Location ID: #335879

Inspection Date: January 11, 2019



**Photo #7 – 400 bbl steel ASTs inside of lined, metal SPCC contain produced water (left tank) and condensate (right tank).**



**Photo #8 – Tear in liner for 400 bbl ASTs was observed on south end of SPCC.**

## Inspection Photos

Location Name: Boies-62S98W 28SESE (#C-28P) Pad

Location ID: #335879

Inspection Date: January 11, 2019



**Photo #9 – Horizontal heated separator located on north side of pad.**



**Photo #10 – View of wellhead and day tank with secondary containment device.**



## Inspection Photos

Location Name: Boies-62S98W 28SESE (#C-28P) Pad

Location ID: #335879

Inspection Date: January 11, 2019



**Photo #11 – View into excavation on land adjacent to pad on the east side. Operator had requested COGCC permission to store cuttings in this area.**



**Photo #12 – View of southwest corner of proposed cuttings management area.**