

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/14/2019

Submitted Date:

01/14/2019

Document Number:

689702415

FIELD INSPECTION FORM

Loc ID 324001 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|-------|---------------------------------------|---------------------------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| , Caerus Piceance | | COGCC.inspections@caerusoilandgas.com | Piceance inspections only |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 211460 | WELL | SI | 01/01/2018 | GW | 045-07220 | TEXACO FEE 6217 | SI |

General Comment:

Follow up to 11/15/2018 inspection # 689702074

Location

| | | | |
|--------------------|-------------------|--------|-------|
| Lease Road: | | | |
| | Type | Access | |
| | comment: | | |
| | Corrective Action | | Date: |
| | Type | Main | |
| | comment: | | |
| | Corrective Action | | Date: |

Overall Good:

| | | | |
|----------------------|--------------------|---|-------|
| Signs/Marker: | | | |
| | Type | CONTAINERS | |
| | Comment: | Unlabeled containers have been removed from battery site. | |
| | Corrective Action: | | Date: |
| | Type | BATTERY | |
| | Comment: | 911 added to sign. | |
| | Corrective Action: | | Date: |
| | Type | WELLHEAD | |
| | Comment: | | |
| | Corrective Action: | | Date: |
| | Type | TANK LABELS/PLACARDS | |
| | Comment: | Unlabeled motor oil tank has been removed. | |
| | Corrective Action: | | Date: |

| | | | |
|---------------------------|--------------------|----------------|-------------|
| Emergency Contact Number: | | | |
| | Comment: | 1-800-791-7691 | |
| | Corrective Action: | | Date: _____ |

| | | | |
|---------------------------|--------------------|--|-------|
| Good Housekeeping: | | | |
| | Type | DEBRIS | |
| | Comment: | Debris and weeds cleaned up. | |
| | Corrective Action: | | Date: |
| | Type | UNUSED EQUIPMENT | |
| | Comment: | Unused equipment has been removed from battery site. | |
| | Corrective Action: | | Date: |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: Spills at separator on well site and compressor at battery site have been cleaned up.

Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 3 | 300 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | Berm has been cleaned up and 500 gallon motor oil tank has been removed. | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|----------|--|
| Type | |
| Comment: | |

Corrective Action:

Date:

Inspected Facilities

Facility ID: 211460 Type: WELL API Number: 045-07220 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Ditches | Pass | | | |
| | | Compaction | Pass | | | |
| | | Culverts | Pass | | | |
| Gravel | Pass | | | | | |
| Compaction | Pass | | | | | |

Comment:

Corrective Action:

Date: 02/15/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 689702416 | Inspection 689702415 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4703958 |