

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/14/2019

Submitted Date:

01/16/2019

Document Number:

675001753**FIELD INSPECTION FORM**Loc ID 312464 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Colby, Lou		lou.colby@state.co.us	
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
, DNR		dnr_cogccengineering@state.co.us	All Engineering
Jordan Ried		maralextechjr@gmail.com	All Inspections
Graves, Jim		mrinc20@qwestoffice.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221691	WELL	SI	09/01/2017	GW	077-08293	USA 1-14 HC	SI

General Comment:This is a follow up inspection to FIR Doc#675203563 dated 11-8-2016
Any corrective actions not addressed from previous inspections are still applicable.

Unmarked risers and deadmen put people at risk of harm in this area.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/ 970/858/8550			
Corrective Action:				Date: _____
Good Housekeeping:				
Type				
Comment:	Unmarked risers and deadmen			
Corrective Action:	Comply with Rule 603.f .			Date: 04/16/2019
Type	UNUSED EQUIPMENT			
Comment:	unused unmarked Risers			
Corrective Action:	Comply with Rule 603.f .			Date: 04/15/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Equipment:				
Type: Gas Meter Run	# 1			corrective date
Comment:	Meter run is partially unhooked.			
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 221691 Type: WELL API Number: 077-08293 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: No production on file. No MIT on file. Listed as corrective action on Previous inspection
Doc#675201663

Corrective Action: Contact COGCC Engineer if over 5 year date or Fails MITDate: 11/21/2016

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Compaction				

Comment: Location has grass and weed growth over entire locationCorrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
This location only has a wellhead and a dismantles meter run. there are several unmarked risers sticking up out of the ground and unmarked risers. Grass and weeds cover entire location	wentzeld	01/14/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675001754	Inspection 675001753 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4705696