

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/09/2019

Submitted Date:

01/10/2019

Document Number:

689302912

FIELD INSPECTION FORM

Loc ID 414152	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
------------------	---------------------------------	---	-------------------

Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	Pipeline group
		COGCC.inspections@caerusoilandgas.com	all Piceance inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413361	WELL	PR	07/31/2011	GW	045-18788	Rulison Federal 20-11C (17M)	PR
413367	WELL	PR	09/23/2011	GW	045-18782	Double B Ranch 18-44A (17M)	PR
413368	WELL	PR	01/18/2012	GW	045-18781	Rulison Federal 20-11A (17M)	PR
413369	WELL	PR	08/03/2011	GW	045-18780	Rulison Federal 20-11B (17M)	PR
413372	WELL	PR	09/01/2011	GW	045-18777	Double B Ranch 18-44B (17M)	PR
413373	WELL	PR	08/29/2011	GW	045-18776	Double B Ranch 18-44C (17M)	PR
413374	WELL	PR	09/01/2011	GW	045-18775	Double B Ranch 18-44D (17M)	PR
413377	WELL	PR	07/15/2011	GW	045-18772	Rulison Federal 19-41C (17M)	PR

General Comment:

Routine Field Inspection.
Location is snow covered, access is plowed open.

ANY CORRECTIVE ACTION (S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:	1-800-580-9382	Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Several unused 2" risers near separators, see photos		
Corrective Action:	Comply with rule 603.f.	Date:	02/09/2019
Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panel fence.		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 7		corrective date
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	400 BBLs	STEEL AST		,	
Comment:	6 tanks in a centralized battery.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	413361	Type:	WELL	API Number:	045-18788	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	413367	Type:	WELL	API Number:	045-18782	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	413368	Type:	WELL	API Number:	045-18781	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	413369	Type:	WELL	API Number:	045-18780	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	413372	Type:	WELL	API Number:	045-18777	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	413373	Type:	WELL	API Number:	045-18776	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	413374	Type:	WELL	API Number:	045-18775	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	413377	Type:	WELL	API Number:	045-18772	Status:	PR	Insp. Status:	PR

Producing Well			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401900054	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4699526
689302913	Inspection photo 689302913	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4699521