

Inspection Photos
Location Name: Lark 33-5 #21-4
API: 05-007-06323



Prime mover exhaust routed underground.



Prime mover exhaust pipe routed underground, reportedly for noise control.

Inspection Photos
Location Name: Lark 33-5 #21-4
API: 05-007-06323



Two five gallon buckets of engine oil stored in secondary containment for lube oil container.



Tubing trailer stored on site during this inspection.

Inspection Photos
Location Name: Lark 33-5 #21-4
API: 05-007-06323



400 bbl. produced water AST installed since last inspection.



AST is stained and NFPA placard has zeros for all fields.

Inspection Photos
Location Name: Lark 33-5 #21-4
API: 05-007-06323



Liner in secondary containment berm for 400 bbl. AST.



NFPA placard for corrosion inhibitor chemical container has zeros for all fields.