

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/18/2019

Submitted Date:

01/18/2019

Document Number:

691201083

FIELD INSPECTION FORM

Loc ID 328688 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248508	WELL	TA	06/01/2018	OW	123-16306	SINJIN E 36-13	TA

General Comment:

Follow-up to FIR #691200973 dated 12/17/2018.
1 of 1 Corrective Action items have been addressed.
1 new Corrective Action item documented.
Well is TA. Master valve is closed.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	SI/TA well per Alternative Mechanical Integrity Assurance Program. Doc #02385001 (NOBLE) . Orange tag for SI/TA status not present. Master valve / Casing valve NOT LOTO.		
Corrective Action:	Install tags / LOTO to comply with Doc #02385001.		Date:

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:			Date:

Equipment:			corrective date
Type: Other	#		
Comment:	WELLHEAD & Master valve.		
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.435386,-104.611749
Comment:	Did NOT inspect Centralized Battery.				
Corrective Action:					Date:

Paint			
Condition	<input type="text"/>		
Other (Content)	<input type="text"/>		

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date: <input style="width:100px;" type="text"/>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: <input style="width:100px;" type="text"/>

Flaring:

Type		
Comment:		
Corrective Action:		Date: <input style="width:100px;" type="text"/>

Inspected Facilities

Facility ID: 248508 Type: WELL API Number: 123-16306 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA. Wellhead has been disconnected from flowline.
COGCC records indicate last production: 05/2015.
SI/TA. MIT requirement waived per Alternative Mechanical Integrity Assurance Program.
Doc #02385001 (NOBLE)

Corrective Action: Date:

BradenHead

Comment: Bradenhead appears plumbed to surface.

Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201084	Site photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707912