

**Inspection Photos**  
**Location Name: GE 34-03**  
**Location ID: 307294**



**Photo 1 SEP**



**Photo 2 WH/PU**

**Inspection Photos**  
**Location Name: GE 34-03**  
**Location ID: 307294**



**Photo 3 Stained soil around cement base of PU**



**Photo 4 Stained soil around liquid ring skid**



**Inspection Photos**  
**Location Name: GE 34-03**  
**Location ID: 307294**



**Photo 5 Stained soil around base of liquid ring skid**