

Inspection Photos
Location Name: GE 28-16
Location ID: 308409



Photo 1 Sep

Photo 2 WH packing leaking at time of inspection

Inspection Photos
Location Name: GE 28-16
Location ID: 308409




Photo 3 stained soil around HYD motor skid

Photo 4 Stained soil around HYD motor skid

Inspection Photos
Location Name: GE 28-16
Location ID: 308409



Colorado Oil and Gas Conservation Commission
37.13857, -104.88515, 2154.5m
Jan 18, 2019 09:34:20



Colorado Oil and Gas Conservation Commission
37.13867, -104.88509, 2147.7m
Jan 18, 2019 09:35:17

Photo 5 stained soil around HYD motor skid

Photo 6 stained soil in back of separator house under 1" drain line for separator.