

**Inspection Photos**  
**Location Name: GE 28-14**  
**Location ID: 311967**



**Photo 1 Sep**

**Photo 2 loc pic and unused equipment 15 BBL tank**

**Inspection Photos**  
**Location Name: GE 28-14**  
**Location ID: 311967**



Colorado Oil and Gas Conservation Commission  
37.13885, -104.89278, 2178.9m  
Jan 18, 2019 10:05:06



Colorado Oil and Gas Conservation Commission  
37.13885, -104.89277, 2188.5m  
Jan 18, 2019 10:05:46

**Photo 3 stained soil around WH**

**Photo 4 stained soil around WH**

**Inspection Photos**  
**Location Name: GE 28-14**  
**Location ID: 311967**



Colorado Oil and Gas Conservation Commission  
37.13886, -104.8928, 2185.2m  
Jan 18, 2019 10:06:04




Colorado Oil and Gas Conservation Commission  
37.1389, -104.89276, 2187.6m  
Jan 18, 2019 10:06:47

**Photo 5 stained soil around HYD motor skid**

**Photo 6 Stained soil around liquid ring skid**


**Inspection Photos**  
**Location Name: GE 28-14**  
**Location ID: 311967**



**Photo 7 stained soil around liquid ring skid**

**Photo 8 Stained soil around liquid ring skid**

**Inspection Photos**  
**Location Name: GE 28-14**  
**Location ID: 311967**



Colorado Oil and Gas Conservation Commission  
37.13897, -104.89281, 2175.6m  
Jan 18, 2019 10:11:51



Colorado Oil and Gas Conservation Commission  
37.13897, -104.89274, 2186.7m  
Jan 18, 2019 10:08:22

**Photo 9 stained soil around liquid ring skid took soil sample**

**Photo 10 30BBL produced water tank**