

**Inspection Photos**  
**Location Name: GE 33-04**  
**Location ID: 309416**




**Photo 1 sep. Location sign is faded needs to be replaced**



**Photo 2 sound walls for liquid ring compressor and 30 BBL production tank**

**Inspection Photos**  
**Location Name: GE 33-04**  
**Location ID: 309416**



**Photo 3 Stained soil and fluid dripping out of liquid ring skid**



**Photo 4 Stained soil and fluid dripping out of liquid ring skid**



**Inspection Photos**  
**Location Name: GE 33-04**  
**Location ID: 309416**



**Photo 5 sound wall panel laying on ground**



**Photo 6 electric fence around lined pit in disrepair**

**Inspection Photos**  
**Location Name: GE 33-04**  
**Location ID: 309416**



**Photo 7 WH and motor skid**