

Inspection Photos
Location Name: GE 29-09-02
Location ID:309302



Photo 1 SEP



Photo 2 WH/ HYD motor sound walls

Inspection Photos
Location Name: GE 29-09-02
Location ID:309302



Photo 3 stained soil under 1" drain line for separator



Photo 4 Electric fence around lined pit in disrepair

Inspection Photos
Location Name: GE 29-09-02
Location ID:309302



Photo 3 stained soil under HYD motor skid