

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/18/2019

Submitted Date:

01/18/2019

Document Number:

688401109

**FIELD INSPECTION FORM**

Loc ID 309416 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 1001 17TH STREET #1000  
City: DENVER State: CO Zip: 80202

**Findings:**

- 14 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
Amato, Joseph	719-845-2110/719-859-2263	josephamato@tcenergy.us	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	
Beardslee, Tom		tom.beardslee@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294730	WELL	PR	02/27/2008	GW	071-09507	GOLDEN EAGLE 33-04	PR

**General Comment:**

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Sign not legible		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	02/18/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil around liquid ring compressor		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A	Date:	02/18/2019
Type	OTHER		
Comment:	Materials handling and spill prevention procedures and practices.		
Corrective Action:	Comply with COGCC rule 1002 F (2) B	Date:	01/22/2019
Type	TRASH		
Comment:	sound wall pannel laying on ground		
Corrective Action:	Comply with Rule 603.f .	Date:	02/01/2019
Type	OTHER		
Comment:	Self-inspection, maintenance and good house keeping procedures and schedules.		
Corrective Action:	Comply with COGCC rule 1002 F (2) D Provide COGCC with pocedure and maintenance documentation within 48hrs	Date:	01/22/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PIT		
Comment:	Fencing around lined pit in disrepair		
Corrective Action:	Location is within a designated setback location, install fencing per Rule 604.c.(2)M.	Date:	02/08/2019

<b>Equipment:</b>			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	HYD motor skid		
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	Liquid ring		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	30BBL	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other				
Comment:	None			
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 294730 Type: WELL API Number: 071-09507 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Comment: Appears to be plumbed to surface

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: SW      Other: \_\_\_\_\_      Length: 30      Width: 30

**Lining:**

Liner Type: Plastic      Liner Condition: Adequate

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Other      Fencing Condition: Inadequate

Comment: electric fence in disrepair

Corrective Action: Location is within a designated setback location, install fencing per Rule 604.c.(2)M.

Date: 02/08/2019

**Netting:**

Netting Type:      Netting Condition:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Anchor Trench Present: YES      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment:

Corrective Action:

Date: \_\_\_\_\_

Permit:	Facility ID	Permit Num	Expiration Date
	296666	1881474	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401110	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707971">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707971</a>