

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/18/2019

Submitted Date:

01/18/2019

Document Number:

695100056

FIELD INSPECTION FORM

Loc ID 307292 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ash, Margaret		margaret.ash@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Amato, Joseph	719-845-2110/719-859-2263	josephamato@tcenergy.us	All Inspections
Gomez, Jason		jason.gomez@state.co.us	
Kosola, Jason		jason.kosola@state.co.us	
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217394	WELL	PR	02/06/2009	GW	071-06170	APACHE CANYON 12-5	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	LOCATION SIGN		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Self-inspection, maintenance and good house keeping procedures and schedules. Materials handling and spill prevention procedures and practices.		
Corrective Action:	Comply with COGCC rule 1002 F (2) B Comply with COGCC rule 1002 F (2) D Provide COGCC with pocedure and maintenance documentation within 48hrs	Date:	01/22/2019
Type	OTHER		
Comment:	HOLE ON LOWEST CORNER OF COMPRESSOR SKID APPEARS TO HAVE STAINED SOIL INSIDE AND ALL AROUND THE HOLE. SPOIL PILE APPEARS TO HAVE COME FROM HOLE THAT WAS DUG ON LOWEST CORNER OF COMPRESSOR SKID ALSO APPEARS TO BE STAINED SOIL. STAINED SOIL ALL AROUND COMPRESSOR SKID APPEARS THAT THERE IS STAINED SOIL ALL UNDER SKID		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.	Date:	01/22/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Compressor	# 1		corrective date
Comment:	WELL APPEARS TO BE PRODUCED BY VACUUM. NO SUNDRY NOTICE ON RECORD.		
Corrective Action:	COMPLY WITH RULE 331.	Date:	02/18/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
------	--	--	--

Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities

Facility ID: 217394 Type: WELL API Number: 071-06170 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Comment:

Corrective Action:

Date: