

Interim Reclamation and Stormwater Inspection

January 9, 2019

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 451353

Inspection Document #: 682404423

Weld County, CO

SWSW Section 11 T3N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Longhorn /14-11
Location ID: 451353



Photo 1. Photo taken from the entrance of the location, facing East. Photo illustrates Operator signs.



Photo 2. Photo taken from the southwest location, facing Southeast. Operator has performed interim reclamation activities with the evidence of drilling rows and straw crimped mulch. Interim areas appear to be properly contoured to the surrounding landscape.

Inspection Photos
Location Name: Longhorn /14-11
Location ID: 451353



Photo 3. Photo taken from the southern location, facing East. See comments under Photo 2.



Photo 4. Photo taken from the interim reclamation area. See comments under Photo 2.

Inspection Photos
Location Name: Longhorn /14-11
Location ID: 451353



Photo 5. Photo taken from the eastern location, facing North. See comments under Photo 2.



Photo 6. Photo taken from the northern location, facing West. Cut slope is not stabilized.

Inspection Photos
Location Name: Longhorn /14-11
Location ID: 451353



Photo 7. Photo taken from the northwestern location, facing West. Site degradation is occurring due to the lack of stabilization along the cut slope.



Photo 8. Photo taken from the western location, facing South. See comments under Photos 6 & 7.

Inspection Photos
Location Name: Longhorn /14-11
Location ID: 451353



Photo 9. Photo taken from the northwestern production area, facing North. Appears unused equipment needs to be removed.