

Interim Reclamation and Stormwater Inspection

January 9, 2019

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 450210

Inspection Document #: 682404425

Weld County, CO

NWSW Section 26 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Mustang /14-26
Location ID: 450210



Photo 1. Photo taken from the entrance of the location, facing East. Photo illustrates Operator signs.



Photo 2. Photo taken from the southwest location, facing South. Photo illustrates Russian thistle weed debris. More weed debris was observed along the southern and northern perimeter of the location.

Inspection Photos
Location Name: Mustang /14-26
Location ID: 450210



Photo 3. Photo taken from the southeast location, facing East. Operator has performed interim reclamation activities with the evidence of drilling rows and straw crimped mulch. However, interim areas do not appear to be properly contoured to the surrounding landscape- see Photos 5 & 6.



Photo 4. Photo taken from the interim reclamation area. See comments under Photo 3.

Inspection Photos
Location Name: Mustang /14-26
Location ID: 450210



Photo 5. Photo taken from the southern perimeter of the location, facing East. Photo illustrates interim areas do not appear to be properly contoured to the surrounding landscape. Further review is required but Operator may need to perform additional contouring to comply with Rule 1003 standards.

Inspection Photos
Location Name: Mustang /14-26
Location ID: 450210



Photo 6. Photo taken from the southeastern perimeter of the location, facing North. See comments under Photo 5.

Inspection Photos
Location Name: Mustang /14-26
Location ID: 450210



Photo 7. Photo taken from the eastern interim area, facing North. See comments under Photo 3.



Photo 8. Photo taken from the eastern interim area, facing South. See comments under Photo 3.

Inspection Photos
Location Name: Mustang /14-26
Location ID: 450210



Photo 9. Photo taken from the northern location, facing West. Tackifier was observed on the cut slope but appears to be in need of maintenance.



Photo 10. Photo taken from the northern location, facing West. See comments under Photo 2.