

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/22/2019

Submitted Date:

01/22/2019

Document Number:

689303030**FIELD INSPECTION FORM**

Loc ID 335534 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284083	WELL	PR	11/01/2018	GW	045-12083	VALLEY FARMS D1	PR
284084	WELL	IJ	11/01/2018	DSPW	045-12082	VALLEY FARMS D3	IJ
288635	WELL	PR	11/01/2018	GW	045-13298	VALLEY FARMS D10	PR
290434	WELL	PR	11/01/2018	GW	045-14109	VALLEY FARMS D13	PR

General Comment:[Routine Field Inspection.](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-855-625-9922

Corrective Action:

Date:

Good Housekeeping:

Type	OTHER		
Comment:	Nonlabeled open bucket with unknown contents in battery containmnet, see photo.		
Corrective Action:	Comply with rule 603.f.	Date:	02/01/2019
Type	OTHER		
Comment:	Stained ground in battery containment and by the separator, see photo.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e..	Date:	02/22/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Type: Flow Line	# 1		
Comment:	Water transfer lines.		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:	3 tanks in a centralized containment.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Inadequate	
Comment:	Holes in secondary containment liner, see photos.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 02/22/2019	
Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	6	300 BBLs	STEEL AST		
Comment: 6 tanks in a centralized containment.					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 284083	Type: WELL	API Number: 045-12083	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment:	Well Producing on plunger lift.
----------	---------------------------------

Corrective Action:	
--------------------	--

Date:	
-------	--

Facility ID: 284084	Type: WELL	API Number: 045-12082	Status: IJ	Insp. Status: IJ
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment:	Well Producing on plunger lift.
----------	---------------------------------

Corrective Action:	
--------------------	--

Date:	
-------	--

Facility ID: 290434	Type: WELL	API Number: 045-14109	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment:	Well Producing on plunger lift.
----------	---------------------------------

Corrective Action:	
--------------------	--

Date:	
-------	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303031	Inspection photo 689303031	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4710800