

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/14/2019

Submitted Date:

01/16/2019

Document Number:

675001753

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
312464 _____ Wentzel, Dougo _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Colby, Lou		lou.colby@state.co.us	
Jordan Ried		maralextechjr@gmail.com	All Inspections
Graves, Jim		mrinc20@qwestoffice.net	
, DNR		dnr_cogccengineering@state.co.us	All Engineering
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221691	WELL	SI	09/01/2017	GW	077-08293	USA 1-14 HC	SI

General Comment:

This is a follow up inspection to FIR Doc#675203563 dated 11-8-2016
Any corrective actions not addressed from previous inspections are still applicable.

Unmarked risers and deadmen put people at risk of harm in this area.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/ 970/858/8550		
Corrective Action:			Date: _____
Good Housekeeping:			
Type			
Comment:	Unmarked risers and deadmen		
Corrective Action:	Comply with Rule 603.f .		Date: <u>04/16/2019</u>
Type	UNUSED EQUIPMENT		
Comment:	unused unmarked Risers		
Corrective Action:	Comply with Rule 603.f .		Date: <u>04/15/2019</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Equipment:			
Type:	Gas Meter Run	# 1	corrective date
Comment:	Meter run is partially unhooked.		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 221691 Type: WELL API Number: 077-08293 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: No production on file. No MIT on file. Listed as corrective action on Previous inspection Doc#675201663

Corrective Action: Contact COGCC Engineer if over 5 year date or Fails MIT Date: 11/21/2016

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Compaction						

Comment: Location has grass and weed growth over entire location

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<u>This location only has a wellhead and a dismantles meter run. there are several unmarked risers sticking up out of the ground and unmarked risers. Grass and weeds cover entire location</u>	wentzeld	01/14/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401907243	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4705700
675001754	Inspection 675001753 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4705696