

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/17/2019

Submitted Date:

01/17/2019

Document Number:

679702688**FIELD INSPECTION FORM**
 Loc ID 316018 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10539Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORPAddress: 1125 ESCALANTE DRCity: RANGELY State: CO Zip: 81648**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone        | Email                       | Comment                         |
|-----------------|--------------|-----------------------------|---------------------------------|
| , Utah Gas Corp | 720-425-0303 | inspections@utahgascorp.com | <a href="#">All inspections</a> |
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us  |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name          | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 231929      | WELL | PR     | 07/20/1993  | GW         | 103-09600 | DRAGON TRAIL UNIT 1145 | PR          |

**General Comment:**[routine well inspection](#)

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 970-693-6021

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | UNUSED EQUIPMENT                                      |       |            |
| Comment:           | Unused equipment frame at northwest edge of location. |       |            |
| Corrective Action: | Comply with Rule 603.f .                              | Date: | 04/22/2019 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                          |   |       |                 |
|--------------------------|---|-------|-----------------|
| <b>Equipment:</b>        |   |       | corrective date |
| Type: Deadman # & Marked | # 3   |       |                 |
| Comment:                 |   |       |                 |
| Corrective Action:       |   | Date: |                 |
| Type: Vertical Separator | # 1   |       |                 |
| Comment:                 |   |       |                 |
| Corrective Action:       |   | Date: |                 |
| Type: Gas Meter Run      | # 2   |       |                 |
| Comment:                 | 1 gas meter building has flowline disconnected. |       |                 |
| Corrective Action:       |   | Date: |                 |
| Type: Plunger Lift       | # 1   |       |                 |
| Comment:                 |   |       |                 |
| Corrective Action:       |   | Date: |                 |

**Tanks and Berms:**

|                    |   |          |          |         |                       |  |
|--------------------|---|----------|----------|---------|-----------------------|--|
| Contents           | # | Capacity | Type     | Tank ID | SE GPS                |  |
| PRODUCED WATER     | 1 | <50 BBLS | Open Top |         | 39.855380,-108.858650 |  |
| Comment:           |   |          |          |         |                       |  |
| Corrective Action: |   |          |          |         | Date:                 |  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 25 bbl   |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|                             |                                |                       |            |                  |
|-----------------------------|--------------------------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |                                |                       |            |                  |
| Facility ID: 231929         | Type: WELL                     | API Number: 103-09600 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |                                |                       |            |                  |
| Comment:                    | producing well on plunger lift |                       |            |                  |
| Corrective Action:          |                                |                       |            | Date:            |

|  |  |  |  |  |
|--|--|--|--|--|
|  |  |  |  |  |
|--|--|--|--|--|

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 |                         |                       |               |                          |         |
| Compaction       |                 | Compaction              |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401909831    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707344">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707344</a> |
| 679702689    | inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707332">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707332</a> |