

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/17/2019

Submitted Date:

01/17/2019

Document Number:

689303008

FIELD INSPECTION FORM

Loc ID 335157 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10531

Name of Operator: VANGUARD OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

22 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman
Collett, Shane		scollett@vnrenergy.com	Superintendent operations
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292114	WELL	PR	05/20/2008	GW	045-14600	SPECIALTY 34A-21-692	PR
292945	WELL	PR	05/27/2008	GW	045-14819	SPECIALTY 34C-21-692	PR
292946	WELL	PR	05/23/2008	GW	045-14820	SPECIALTY 33C-21-692	PR
292947	WELL	PR	05/30/2008	GW	045-14821	SPECIALTY 44C-21-692	PR
292948	WELL	PR	08/11/2008	GW	045-14822	SPECIALTY 43A-21-692	PR
292949	WELL	PR	08/10/2008	GW	045-14823	SPECIALTY 43C-21-692	PR
292950	WELL	PR	07/31/2008	GW	045-14824	SPECIALTY 44A-21-692	PR
292951	WELL	PR	05/25/2008	GW	045-14825	SPECIALTY 33A-21-692	PR

General Comment:

Routine Field Inspection.

Location

Lease Road:			
Type	Access		
comment:	Snow packed.		
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-921-8252

Corrective Action:

Date:

Good Housekeeping:

Type	OTHER		
Comment:	Stained ground under scrubber pot. Also stained ground under fittings on separators.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.	Date:	01/21/2019

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Panel gates		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Horizontal Heated Separator	# 16		
Comment:	Dripping fittings on unit 43C and 34A, see photo.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 01/21/2019
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		

Comment:		Chemical unit at wellhead.			
Corrective Action:				Date:	
Type: Plunger Lift	# 8				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	10	500 BBLs	STEEL AST		,	
Comment:		10 tanks in a centralized containment. 2 tanks are heated.				
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open top vent per sundry notice.		
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	292114	Type:	WELL	API Number:	045-14600	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	292945	Type:	WELL	API Number:	045-14819	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	292946	Type:	WELL	API Number:	045-14820	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	292947	Type:	WELL	API Number:	045-14821	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	292948	Type:	WELL	API Number:	045-14822	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	292949	Type:	WELL	API Number:	045-14823	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	292950	Type:	WELL	API Number:	045-14824	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	292951	Type:	WELL	API Number:	045-14825	Status:	PR	Insp. Status:	PR

Producing Well			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401909834	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707347
689303009	Inspection photo 689303009	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707340