

Construction and Stormwater Inspection

January 16, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - #10633

Location ID: 451044

Inspection Document #: 682404466

Weld County, CO

NWNE Section 19 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Regnier Farms /19H-B268 Wells

Location ID: 451044



Photo 1. Photo taken from the western location, facing Northwest. Photo illustrates the western topsoil stockpile. Operator was still salvaging topsoil from the northern location. Based on field observations, it appears the Operator is salvaging all topsoil from disturbance areas.

Inspection Photos
Location Name: Regnier Farms /19H-B268 Wells
Location ID: 451044



Photo 2. Photo taken from the western topsoil stockpile, facing East. Photo illustrates salvage operations underway along the northern location.

Inspection Photos
Location Name: Regnier Farms /19H-B268 Wells
Location ID: 451044



Photo 3. Photo taken from the central location, facing Northwest. Photo illustrates the original surface height compared to how much topsoil is being salvaged. Appears about 15” of topsoil has been salvaged from the location.

Inspection Photos
Location Name: Regnier Farms /19H-B268 Wells
Location ID: 451044



Photo 4. Photo taken from the entrance of location, facing West. Photo illustrates there is no vehicle track out issues. Operator is still constructing the access road and has additional vehicle tracking device BMPs planned.

Inspection Photos
Location Name: Regnier Farms /19H-B268 Wells
Location ID: 451044



Photo 5. Photo taken from the entrance of location, facing South. See comments under Photo 4.