

Inspection Photos

API: 05-009-06661

Operator: BAYHORSE PETROLEUM LLC

Inspection Date: 1/18/2019

Inspection Photos



Photo 1. West side of the location facing east.

Inspection Photos



Photo 2. Facing east at the east side of the location. Vegetation has not established in this area approximately 100'x150'.

Inspection Photos



Photo 3. East side of the location facing west.

Inspection Photos



Photo 4. Northeast side of the location facing southwest.

Inspection Photos



Photo 5. Facing south toward the undisturbed vegetation.