

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/09/2019

Submitted Date:

01/24/2019

Document Number:

688000243

FIELD INSPECTION FORM

Loc ID 313944 Inspector Name: YOUNG, ROB On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 95620
Name of Operator: WESTERN OPERATING COMPANY
Address: 1165 DELAWARE STREET #200
City: DENVER State: CO Zip: 80204

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|----------------|----------------------------|---------------------------------|
| James, Steven | (303) 893-2438 | steve@westernoperating.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|--------------------------|-------------|
| 313944 | LOCATION | AC | | | - | CHALLIS-64N59W 34NWSE | EI |

General Comment:

[Environmental inspection. Small area of wet soil on the north side of the crude oil tank appears to be from a corrosion hole in the tank.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

| Spills: | | | | |
|----------------|------|--------|--|--|
| Type | Area | Volume | | |
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|----------|-----------|---------|------------------|
| CRUDE OIL | 1 | 200 BBLs | STEEL AST | | |
| Comment: | Moist soil on the north side base of the crude oil ast appears to be from a small leak in the tank. | | | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Provide an eForm 27 describing the sampling of impacted soil and potentially impacted soil beneath the crude oil tank. | | | | Date: 01/31/2019 |

Paint

| | |
|------------------|----------------------|
| Condition | <input type="text"/> |
| Other (Content) | <input type="text"/> |
| Other (Capacity) | <input type="text"/> |
| Other (Type) | <input type="text"/> |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------------------|---------------------|---------------------|----------------------------|
| | | | | |
| Comment: | <input type="text"/> | | | |
| Corrective Action: | <input type="text"/> | | | Date: <input type="text"/> |

Venting:

| | | |
|--------------------|----------------------|----------------------------|
| Yes/No | <input type="text"/> | <input type="text"/> |
| Comment: | <input type="text"/> | |
| Corrective Action: | <input type="text"/> | Date: <input type="text"/> |

Flaring:

| | |
|--------------------|----------------------------|
| Type | <input type="text"/> |
| Comment: | <input type="text"/> |
| Corrective Action: | Date: <input type="text"/> |

Inspected Facilities

Facility ID: 313944 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 688000244 | Location photographs | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4714114 |