



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Location sign		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil around HYD motor skid		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A	Date:	02/18/2019
Type	OTHER		
Comment:	stained soil under 1"line for drain to seperator.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	02/18/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	HYD motor skid		
Corrective Action:		Date:	

Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 288297 Type: WELL API Number: 071-09113 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Comment: Appears to be plumbe to surface

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: SW      Other: \_\_\_\_\_      Length: 35      Width: 30

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: None      Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:      Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:      Oil Accumulation:      2+ feet Freeboard:

Comment:

Corrective Action

Date:

**COGCC Comments**

Comment	User	Date
<a href="#">At time of inspection pumber on site drained seperator onto ground. See video.</a>	silverr	01/18/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401911093	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707984">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707984</a>
688401112	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707972">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707972</a>
688401113	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707973">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707973</a>
688401114	Loc video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707974">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707974</a>
688401115	loc video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707975">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707975</a>