

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/18/2019

Submitted Date:

01/18/2019

Document Number:

691201083**FIELD INSPECTION FORM**
 Loc ID 328688 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name   | Phone | Email                                  | Comment                         |
|----------------|-------|--|---------------------------------|
| ,              |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM | <a href="#">All Inspections</a> |
| Pesicka, Conor |       | conor.pesicka@state.co.us              |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 248508      | WELL | TA     | 06/01/2018  | OW         | 123-16306 | SINJIN E 36-13 | TA          |

**General Comment:**

Follow-up to FIR #691200973 dated 12/17/2018.  
 1 of 1 Corrective Action items have been addressed.  
 1 new Corrective Action item documented.  
 Well is TA. Master valve is closed.

### Location

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Lease Road:</b> |          |       |  |
| Type               | Access   |       |  |
| comment:           | Adequate |       |  |
| Corrective Action  | L        | Date: |  |

Overall Good: ☐

|                      |   |       |  |
|----------------------|---|-------|--|
| <b>Signs/Marker:</b> |   |       |  |
| Type                 | OTHER   |       |  |
| Comment:             | SI/TA well per Alternative Mechanical Integrity Assurance Program. Doc #02385001 (NOBLE) . Orange tag for SI/TA status not present. Master valve / Casing valve NOT LOTO. |       |  |
| Corrective Action:   | Install tags / LOTO to comply with Doc #02385001.   | Date: |  |
| Type                 | WELLHEAD  |       |  |
| Comment:             |   |       |  |
| Corrective Action:   |   | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

|  |      |        |  |
|--|------|--------|--|
| <b>Spills:</b>   |      |        |  |
| Type   | Area | Volume |  |
| In Containment: No                                     |      |        |  |
| Comment: _____   |      |        |  |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |  |

|                    |            |       |  |
|--------------------|------------|-------|--|
| <b>Fencing/:</b>   |            |       |  |
| Type               | WELLHEAD   |       |  |
| Comment:           | Iron panel |       |  |
| Corrective Action: |            | Date: |  |

|                    |                          |       |                 |
|--------------------|--------------------------|-------|-----------------|
| <b>Equipment:</b>  |                          |       | corrective date |
| Type: Other        | #                        |       |                 |
| Comment:           | WELLHEAD & Master valve. |       |                 |
| Corrective Action: |                          | Date: |                 |

**Tanks and Berms:**

| Contents                                      | # | Capacity | Type                | Tank ID | SE GPS                |
|---|---|----------|---------------------|---------|-----------------------|
|   |   |          | CENTRALIZED BATTERY |         | 40.435386,-104.611749 |
| Comment: Did NOT inspect Centralized Battery. |   |          |                     |         |                       |
| Corrective Action:                            |   |          |                     |         | Date:                 |

**Paint**

|                 |  |
|-----------------|--|
| Condition       |  |
| Other (Content) |  |

|                  |  |  |  |  |  |
|------------------|--|--|--|--|--|
| Other (Capacity) |  |  |  |  |  |
| Other (Type)     |  |  |  |  |  |

**Berms**

|                    |          |                     |                     |             |  |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |  |
|                    |          |                     |                     |             |  |
| Comment:           |          |                     |                     |             |  |
| Corrective Action: |          |                     |                     | Date:       |  |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**Facility ID: 248508 Type: WELL API Number: 123-16306 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA. Wellhead has been disconnected from flowline.  
COGCC records indicate last production: 05/2015.  
SI/TA. MIT requirement waived per Alternative Mechanical Integrity Assurance Program.  
Doc #02385001 (NOBLE)

Corrective Action:  Date: **BradenHead**Comment: Bradenhead appears plumbed to surface.Corrective Action:  Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401910921    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707913">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707913</a> |
| 691201084    | Site photo           | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707912">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707912</a> |