

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/29/2019

Submitted Date:

01/29/2019

Document Number:

679600273

FIELD INSPECTION FORM

Loc ID 330783 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10629
Name of Operator: FIFTH CREEK ENERGY OPERATING COMPANY LLC
Address: 5251 DTC PKWY STE 420
City: GREENWOOD State: CO Zip: 80111

Findings:

- 6 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Barber, Matt		mbarber@hpres.com	All Inspections
Kraich, Adam		adam.kraich@state.co.us	
,		birwin@fifthcreekenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251813	WELL	PR	02/01/2018	OW	123-19617	COLORADO ENERGY FEDERAL 14-3	SI

General Comment:

Location						
Overall Good: <input checked="" type="checkbox"/>						
Signs/Marker:						
Type	WELLHEAD					
Comment:	Sign not updated to reflect current operator. See attached photo.					
Corrective Action:	Install sign to comply with Rule 210.e.				Date:	03/01/2019
Emergency Contact Number:						
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>
Good Housekeeping:						
Type	DEBRIS					
Comment:	Door from pump jack shed is off and on ground. See attached photo.					
Corrective Action:	Comply with Rule 603.f .				Date:	03/01/2019
Overall Good: <input type="checkbox"/>						
Spills:						
Type	Area	Volume				
In Containment: No						
Comment:	<input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?						
Fencing/:						
Type	PUMP JACK					
Comment:	Wire. Inadequate fencing or Fencing in disrepair. See attached photo.					
Corrective Action:	Comply with Rule 603.f .				Date:	03/01/2019
Equipment:						
Type: Deadman # & Marked	# 4				corrective date	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>
Type: Ancillary equipment	# 1					
Comment:	Pump jack shed. At time of inspection, what appears to be stained soil inside pump jack shed around prime mover.					
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.				Date:	<input type="text"/>
Type: Pump Jack	# 1					
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>
Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0				,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>
Paint						

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 251813 Type: WELL API Number: 123-19617 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679600277	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4718770