

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2019

Submitted Date:

01/30/2019

Document Number:

687903691

FIELD INSPECTION FORM

Loc ID 311924 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10464
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
Address: 1801 BROADWAY #1000
City: DENVER State: CO Zip: 80202

Findings:

- 10 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Reed	720-484-2346	Inspections@catamountep.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216305	WELL	PR	09/01/2017	GW	067-07911	OLSON-SMITH GAS UNIT 2	PR
295725	WELL	PR	09/12/2017	GW	067-09545	IGE 127	PR

General Comment:

[Conducted inspection with SW FIU Supervisor Steve Labowskie. Downloadable pictures at end of inspection report.](#)

Location					
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:	Framed metal sign.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Emergency contact up to date. (970) 442-6620				Date:
Corrective Action:					Date: _____
Good Housekeeping:					
Type	TRASH				
Comment:	Trash and rags on pump jack skid.				
Corrective Action:	Clean up trash to comply with Rule 603.f.				Date: <u>02/11/2019</u>
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					
Type: Gas Meter Run	# 2				corrective date
Comment:					
Corrective Action:					Date:
Type: Ancillary equipment	# 2				
Comment:	wellhead stuffing box leak.				
Corrective Action:	Repair leak to comply with Rule 605.d.				Date: <u>02/01/2019</u>
Type: Vertical Heated Separator	# 2				
Comment:					
Corrective Action:					Date:
Type: Pump Jack	# 2				
Comment:	Pump jack has gearbox leak and a slight puddle on concrete base.				
Corrective Action:	Repair equipment as necessary to comply with rule 605.d and Rule 907.e.				Date: <u>02/08/2019</u>
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,
Comment:	Thief hatch found open at time of inspection.				
Corrective Action:	Comply with Rule 605.d.				Date: <u>02/28/2019</u>
Paint					
Condition	Adequate				

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	<p>Large tear in southern wall secondary containment.</p> <p>Tires in secondary containment.</p>			
Corrective Action:	<p>Repair or replace damaged liner per Rule 605.a.(4).</p> <p>Remove trash to comply with Rule 603.f.</p>			Date: 02/28/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 216305 Type: WELL API Number: 067-07911 Status: PR Insp. Status: PR

Facility ID: 295725 Type: WELL API Number: 067-09545 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687903692	Stuffing box leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719438
687903693	Gear box leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719439
687903694	Gear box leak on concrete	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719440
687903695	Tires in secondary	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719441
687903696	Compromised liner tear	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719442