

Inspection Photos
Location Name: Champlin 117 AMOCO C #6
Location ID: 319839



Photo 1 WH/PU



Photo 2 TNK BTRY

Inspection Photos

Location Name: Champlin 117 AMOCO C #6

Location ID: 319839



Photo 3 load line to west crude oil tank not capped or plugged.

