

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Mechanical issue with load line VLV in back of west crude oil tank		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	02/28/2019
Type	DEBRIS		
Comment:	Dead weeds around WH,PU,TNK BTRY,SEP and production tank		
Corrective Action:	Comply with Rule 603.f .	Date:	02/12/2019
Type	OTHER		
Comment:	stained soil around PU motor.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A	Date:	02/28/2019
Type	OTHER		
Comment:	stained soil around load line VLV and bottom of west crude oil tank.		
Corrective Action:	For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e.	Date:	02/28/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Square tubing		

Corrective Action:		Date:	
Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Gas powered motor		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Closed and LOTO		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	VLV closed		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	50BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Inadequate berms around tank(s)			
Corrective Action:	Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.			Date: 02/19/2019

Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	2	400 BBLs	STEEL AST		39.911389,104.562601		
Comment:							
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 201670 Type: WELL API Number: 001-07073 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
This is a follow up inspection per Doc#688504206. All corrective actions have been addressed at time of inspection. Dug down on west crude oil tank could not see leak on tank but there is stained soil at time of inspection. No gas going to ECD VLV is closed.	silverr	01/29/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401157	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4720207