

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/24/2019

Submitted Date:

01/24/2019

Document Number:

695100076

**FIELD INSPECTION FORM**

Loc ID 308808 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10084  
Name of Operator: PIONEER NATURAL RESOURCES USA INC  
Address: 5205 N O'CONNOR BLVD STE 200  
City: IRVING State: TX Zip: 75039

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	<a href="#">All Inspections</a>
Distribution, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282388	WELL	PR	04/03/2006	GW	071-08667	RAZOR CLAM 23-27	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	LOCATION SIGN		
Corrective Action:		Date:	
Type	OTHER		
Comment:	PRODUCED WATER TANK LABEL		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	STAINED SOIL UNDER DRAIN PLUG ON COMPRESSOR SKED. STAINED SOIL AROUND WELLHEAD AND BETWEEN ENGINE SKID.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. DO TO EXPECTED ADVERSE WEATHER CONDITIONS IM EXTENDING THE CORRECTIVE ACTION TIMELINE TO 30 DAYS		Date: <u>02/25/2019</u>

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No \_\_\_\_\_

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Compressor	# 1		corrective date
Comment:	WELL APPEARS TO BE PRODUCED ON A VACUUM. NO SUNDRY NOTICE ON RECORD.		
Corrective Action:	COMPLY WITH COGCC RULE 331.		Date: <u>02/25/2019</u>

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	BV PLASTIC		37.142210,-104.658650
Comment:	TANK FOR SEPARATOR DRAIN AT THE METER HOUSE.				
Corrective Action:				Date:	

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	APPROXIMATELY 30 GAL.
Other (Type)	<input type="text"/>

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 282388 Type: WELL API Number: 071-08667 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401917639	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4714345">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4714345</a>
695100077	LOC PICS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4714335">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4714335</a>